



*Servicing Outdoor Power Equipment Dealers Since 1984*  
8 McFadden Road ☎ Easton, PA 18045 ☎ (800) 942-2326 ☎ <https://shop.cadcodist.com/>

# Stinger Information Bulletin

## Stinger Informational Bulletin 2025-2

### Gateway Gen 2 Traction Cable Improvement

Improved traction cable was designed to replace the initial traction cable on Gen 2 Gateways with Honda engines



To reduce the possibility of a traction cable failure, the cable design has been improved and a new replacement spring for the hydraulic pump linkage will supersede the original.

When a failure is encountered, it is recommended to replace the existing traction cable and the black spring located on the hydraulic pump control linkage. Replace them with the improved cable and silver spring – detailed installation instructions will be included with the kit.

Normal warranty applies if the machine is within the warranty period. Cable replacement time is 10min. Familiarize yourself with the installation video for efficient installation. An installed replacement cable may not be covered by warranty, due to the fact that it can break from being mis-adjusted.

**Please contact us with any questions on this.**



Link for cable installation instruction video

